

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/24/2012	3. Time Prepared 1500
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief	6. Operational Period 0700, 03/22/12 – 0700, 03/29/12	
7. Personnel Roster Assigned			
Name	ICS Position	Home Base	
Matthew Haak	Situation Unit Leader	Houston, Texas	
8. Activity Log			
Time	Major Events		
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> <li>MP30.0 sheen observed at E4 boat launch. Sheen observed after boat was launched.</li> <li>MP30.0 sheen observed at E4 boat launch. Sheen observed after boat was launched.</li> <li>MP32.0 LDB during river assessment observed absorbent boom from last year submerged oil work was observed. SWAT disposed of boom.</li> <li>MP32.0 sheen observed in center of river channel. Typical size of sheen spots observed in river system when observed.</li> <li>MP33.0 LDB former submerged oil location sheen observed.</li> </ul>		
	Additional observations: None		
15:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			